

Instruction Manual

MODEL 8100A

DIGITAL MULTIMETER

Reproduced with Permission from Fluke Corporation



ELECTRONICS FOR INDUSTRY
INSTRUMENTS / COMPONENTS

TABLE OF CONTENTS

SECTION	TITLE	PAGE
I	INTRODUCTION AND SPECIFICATIONS	1-1
	1-1. Introduction	1-1
	1-4. Electrical Specifications	1-1
	1-5. Environmental Specifications	1-2
	1-6. Mechanical Specifications	1-3
	1-7. General Specifications	1-3
II	OPERATING INSTRUCTIONS	2-1
	2-1. Introduction	2-1
	2-3. Installation	2-1
	2-5. Accessories	2-1
	2-7. Input Power Requirements	2-1
	2-10. Operating Features	2-2
	2-12. Operational Check	2-4
	2-15. DC Voltmeter Operation	2-4
	2-17. AC Voltmeter Operation	2-4
	2-19. Ohmmeter Operation	2-5
	2-21. Operating Notes	2-5
	2-22. Overload Protection	2-5
	2-24. Use of Guard Terminal	2-5
	2-26. Applications	2-5
	2-27. Transistor Testing	2-5
	2-29. DBM Measurement	2-5
	2-31. Measurement of High Resistances	2-6
	2-33. Use as a Null Detector	2-6
III	THEORY OF OPERATION	3-1
	3-1. Introduction	3-1
	3-3. General Theory	3-1
	3-4. System Description	3-1
	3-6. Buffer	3-1

(continued on page ii)

TABLE OF CONTENTS, *continued*

SECTION	TITLE	PAGE
	3-12. A/D Converter	3-3
	3-19. Analog Storage	3-5
	3-21. Display	3-5
	3-23. Power Supply and Clock	3-6
3-25.	Circuit Description	3-6
	3-26. Buffer	3-6
	3-31. A/D Converter	3-7
	3-40. Analog Storage	3-9
	3-44. Display	3-10
	3-48. Power Supply	3-10
IV	MAINTENANCE	4-1
	4-1. Introduction	4-1
	4-4. Service Information	4-1
	4-6. Test Equipment	4-1
	4-8. General Maintenance	4-1
	4-9. Access/Disassembly	4-1
	4-11. Fuse Replacement	4-3
	4-13. 115/230 Volt Conversion	4-3
	4-15. Lamp and Tube Replacement	4-3
	4-17. Cleaning	4-3
4-19.	Performance Tests	4-4
	4-21. DC Voltage Test	4-4
	4-23. AC Voltage Test	4-4
	4-25. Ohms Test	4-4
4-27.	Troubleshooting	4-5
	4-29. Power Consumption	4-5
	4-31. Power Supply	4-5
	4-33. Buffer Amplifier	4-6
	4-35. Linearity	4-6
	4-36. Waveforms	4-6
4-38.	Calibration	4-7
	4-40. Adjustment Locations	4-7
	4-42. Preliminary Operations	4-7
	4-43. Zero Adjustment	4-7
	4-44. DC Voltage Calibration	4-7
	4-45. Input Divider Adjustment	4-7
	4-46. Kilohm Calibration	4-7

(continued on page iii)

TABLE OF CONTENTS, *continued*

SECTION	TITLE	PAGE
	4-47. 10 Megohm Calibration	4-8
	4-48. Voltage Calibration and Final Zero Adjustment	4-8
V	LIST OF REPLACEABLE PARTS	5-1
	5-1. Introduction	5-1
	5-4. Column Description	5-1
	5-5. How to Obtain Parts	5-2
	5-8. List of Abbreviations	5-2
	5-9. Serial Number Effectivity	5-21
VI	ACCESSORIES AND OPTIONS	6-1
	6-1. Introduction	6-1
	6-3. Accessories	6-1
	6-4. High Frequency Probe	6-1
	6-6. High Voltage Probes	6-1
	6-8. Switched AC/DC Current Shunts	6-3
	6-10. Front Panel Dust Cover	6-3
	6-12. Rack Mount Kits	6-3
	6-14. Option Information	6-4
	6-15. Introduction	6-4
	6-17. Installation Procedure	6-4
	6-18. Operating Instructions	6-6
	6-21. List of Replaceable Parts	6-6
	APPENDIX A	
	WARRANTY	
	LIST OF SALES REPRESENTATIVES	
	LIST OF FACTORY AUTHORIZED SERVICE CENTERS	
	SCHEMATIC DIAGRAMS	

LIST OF ILLUSTRATIONS

FIGURE	TITLE	PAGE
Frontispiece	Model 8100A Digital Multimeter	vi
1-1.	Model 8100A Outline Drawing	1-3
2-1.	Controls, Terminals, and Indicators (Sheet 1 of 3)	2-2
2-1.	Controls, Terminals, and Indicators (Sheet 2 of 2)	2-3
2-2.	AC Voltage to DBM Conversion Table for 600-Ohm Circuits	2-5
2-3.	Circuit Connections for Measurement of High Resistances	2-6
3-1.	Model 8100A Simplified Block Diagram	3-1
3-2.	DC Voltage Mode Simplified Diagram	3-2
3-3.	Kilohm Mode Simplified Diagram	3-2
3-4.	10 Megohm Mode Simplified Diagram	3-2
3-5.	AC Voltage Mode Simplified Diagram	3-2
3-6.	Buffer Outputs	3-3
3-7.	Recirculating-Remainder A/D Conversion	3-4
3-8.	A/D Converter Simplified Diagram	3-5
3-9.	Analog Storage Simplified Diagram	3-6
3-10.	Display Section Simplified Diagram	3-6
3-11.	Power Supply and Clock Simplified Diagram	3-6
3-12.	Timing Diagram	3-8

(continued on page v)

LIST OF ILLUSTRATIONS, *continued*

FIGURE	TITLE	PAGE
4-1.	Test and Calibration Equipment	4-2
4-2.	DC Voltage Test Requirements	4-4
4-3.	AC Voltage Test Requirements	4-5
4-4.	Ohms Test Requirements	4-5
4-5.	Power Supply Voltage Requirements	4-5
4-6.	Signal Locations and Oscilloscope Settings for Waveform Check . . .	4-6
4-7.	Location of the Major Circuit Areas	4-8
5-1.	8100A Digital Multimeter (Sheet 1 of 2)	5-3
5-1.	8100A Digital Multimeter (Sheet 2 of 2)	5-4
5-2.	Printed Circuit Assembly	5-17
5-3.	Printed Circuit Assembly	5-19
6-1.	High Frequency Probe Characteristics	6-1
6-2.	Model 80F-5/80F-15 High Voltage Probes	6-2
6-3.	Voltage Divider Specifications	6-3
6-4.	Model A90 Current Shunt	6-3
6-5.	Front Panel Dust Cover	6-4
6-6.	Rack Mount Kit	6-4
6-7.	Component Locations for Model 8100A Battery Option Installation	6-5
6-8.	Battery Option Meter Installation	6-5
6-9.	Battery Installation	6-6