

2753P SPECTRUM ANALYZER

Qservice ----- This Document is a complete scan from the Original Tektronix Manual ----- Qservice

Please Check for CHANGE INFORMATION at the Rear of This Manual

First Printing MAY 1987

Tektronix[®]
COMMITTED TO EXCELLENCE

TABLE OF CONTENTS

	Page		Page
PREFACE.....	i	Section 4 (continued)	
TABLE OF CONTENTS.....	iii	Instrument Power Control and	
LIST OF ILLUSTRATIONS.....	v	Frequency.....	4-3
LIST OF TABLES.....	v	Frequency Span and Resolution.....	4-5
SAFETY SUMMARY.....	vi	Marker Functions.....	4-7
Section 1 GENERAL INFORMATION		Display Parameters.....	4-14
Product Overview.....	1-1	Sweep.....	4-17
Firmware Version and Error Message		Digital Storage.....	4-19
Readout.....	1-1	Display and General Purpose.....	4-21
Accessories.....	1-1	Front-panel Input/Output and GPIB.....	4-24
Options.....	1-2	Rear-panel Input/Output and GPIB.....	4-26
Section 2 SPECIFICATION		Section 5 INSTRUMENT CHECK OUT	
Electrical Characteristics.....	2-1	Firmware Version and Error Message	
Verification of Tolerance Values.....	2-1	Readout.....	5-1
Frequency Related Characteristics.....	2-2	Firmware Version.....	5-1
Amplitude Related Characteristics.....	2-4	Error Message Readout.....	5-1
Input Signal Characteristics.....	2-8	Preparation for Use.....	5-1
Output Signal Characteristics.....	2-10	1. Initial Turn On.....	5-1
General Characteristics.....	2-11	2. Calibrate Position, Center	
Power Requirements.....	2-11	Frequency, Reference Level, and	
Environmental Characteristics.....	2-12	Bandwidth.....	5-2
Physical Characteristics.....	2-13	Functional or Operational Check.....	5-3
Section 3 PREPARATION FOR USE		Equipment Required.....	5-3
Unpacking and Initial Inspection.....	3-1	Preliminary Preparation.....	5-3
Installation.....	3-1	1. Check Operation of Front-Panel	
Rackmount Instrument.....	3-1	Pushbuttons and Controls.....	5-3
Rack Adapter Kit.....	3-1	2. Check Gain Variation Between	
Power Source and Power		Resolution Bandwidths.....	5-10
Requirements.....	3-1	3. Check Counter Accuracy.....	5-10
Storage and Repackaging.....	3-2	4. Check Span Accuracy and	
Storage.....	3-2	Linearity.....	5-11
Repackaging for Shipment.....	3-2	5. Check Resolution Bandwidth and	
Section 4 CONTROLS, CONNECTORS,		Shape Factor.....	5-11
AND INDICATORS		6. Check Reference Level Gain and	
Operating Modes.....	4-1	RF Attenuator Steps.....	5-11
Initial Entry Functions (Black Labels) ..	4-1	7. Check Sensitivity.....	5-12
Multiple-Pushbutton Sequence		8. Check Residual FM.....	5-12
Functions (SHIFT Pushbutton).....	4-1	9. Check Frequency Drift or	
Terminating Multiple-Pushbutton		Stability.....	5-13
Sequences.....	4-1	10. GPIB Verification Program.....	5-14
DATA ENTRY Functions (Orange		Section 6 OPERATION	
Labels).....	4-1	Instrument Operating Features.....	6-1
Correcting Numerical Entry Errors.....	4-2	Firmware Version and Error Message	
		Readout.....	6-1
		Crt Light Filters.....	6-1
		Intensity Level and Beam Alignment...6-1	
		Signal Application.....	6-1
		! RF INPUT Connector.....	6-1

	Page
Section 6 (continued)	
Resolution Bandwidth, Frequency Span, and Sweep Time	6-2
Using the Signal Identifier	6-3
Using the Video Filters	6-4
Using Time Domain Operation	6-4
Triggering the Display	6-4
Sweeping the Display	6-4
Manual Scan of the Spectrum	6-5
Reference Level, RF Attenuation, and Vertical Display	6-5
Alternate Reference Level Units Selection	6-5
Using the Delta A Mode	6-5
Using MIN NOISE or MIN DISTORTION	6-6
Using Digital Storage	6-6
Using the Store and Recall Features ..	6-7
Using Signal Count	6-7
Plotting the Display	6-9
Using the Markers Feature	6-9
Marker Terms	6-9
Marker Turn On	6-10
Assigning Markers	6-10
Tuning Markers	6-11
Using the Automatic Performance Testing Feature	6-11
Using the Tracking Generator Mode ..	6-11
Using the Sideband Analyzer Mode ..	6-11
Programming Features (GPIB Operation)	6-11
Setting GPIB Address Switches	6-11
TALK ONLY, LISTEN ONLY Switches	6-12
Personalized Macros	6-12
Operational Considerations/Precautions	6-12
1. ! RF INPUT Power Limit	6-12
2. Instrument Warm-Up After Storage	6-12
3. Auto Resolution	6-12
4. Level of Pulsed Signals	6-12

	Page
Section 6 (continued)	
5. Level of Continuous Wave Signals ..	6-12
6. Excessive Input Signal Level	6-12
7. No Crt Trace	6-13
8. PEAK/AVERAGE	6-13
9. Digital Storage Effects on Signal Analyses	6-13
10. Stored Display Averaged in Wide Spans	6-13
11. TRIGGERING	6-13
12. Oscillator Frequency cannot be set	6-13
Service Information	6-14
Service Manual	6-14
Product Service	6-14
Emergency Repair	6-14
Maintenance Agreements	6-14
Section 7 OPTIONS	
Options A1–A5 (Power Cord Options)	7-1
Option B1 (Service Manuals)	7-1
Options M1–M3 (Extended Service and Warranty Options)	7-2
Option 05 (Provide counter and macros)	7-2
Option 07 ! (Provide 75Ω Input)	7-3
Options 30 and 31 (Provide Rackmount)	7-5
Option 39 (Provide Silver Battery)	7-5
Option 42 (Provide 110 MHz IF Output)	7-5
Option 45 (Provide MATECO Capability)	7-6
Option 52 (Provide North American 220 V)	7-6
Appendix A GLOSSARY	
General Terms	A-1
Terms Related to Frequency	A-1
Terms Related to Amplitude	A-2
Terms Related to Digital Storage	A-3
Terms Related to Markers	A-3

LIST OF ILLUSTRATIONS

Figure Number	Page	Figure Number	Page
2-1	Dimensions	2-13	
4-1	Instrument Power Control and Frequency	4-3	
4-2	Frequency Span and Resolution	4-5	
4-3	Marker Functions	4-7	
4-4	Locating the signal peak	4-8	
4-5	Using FIND PEAK MAX	4-10	
4-6	Signal finding example	4-11	
4-7	Signal finding example	4-11	
4-8	Signal finding example	4-12	
4-9	Signal finding example	4-12	
4-10	Signal finding example	4-13	
4-11	Display Parameters	4-14	
4-12	Sweep	4-17	
4-13	Digital Storage	4-19	
4-14	Display and General Purpose	4-21	
4-15	Front-Panel Input/Output and GPIB	4-24	
4-16	Rear-Panel Input/Output and GPIB	4-26	
5-1	Crt display and readout at initial turn on	5-1	
5-2	Typical display of calibration markers in the maximum span position	5-2	
5-3	Integrating a display with the VIDEO FILTER	5-5	
5-4	Displays that illustrate how bandwidth and shape factor are determined	5-11	
5-5	Typical display showing how to determine residual FM	5-13	
6-1	Circuit of a 75 to 50 Ω matching pad (ac coupled)	6-2	
6-2	Graph illustrating the relationship between dBm, dBmV, and dB	6-2	
6-3	Volts, dBm-Watts conversion chart for 50 Ω impedance	6-3	
6-4	Typical display mixed with the VIDEO FILTER	6-4	
6-5	Typical display using B-SAVE A to observe the difference between SAVE A and B displays	6-6	
7-1	International power cord options for the spectrum analyzer	7-1	

LIST OF TABLES

Table Number	Page	Table Number	Page
2-1	Frequency Related Characteristics	2-2	
2-2	Amplitude Related Characteristics	2-4	
2-3	Input Signal Characteristics	2-8	
2-4	Output Signal Characteristics	2-10	
2-5	General Characteristics	2-11	
2-6	Power Requirements	2-11	
2-7	Environmental Characteristics	2-12	
2-8	Physical Characteristics	2-13	
5-1	Sensitivity	5-12	
6-1	50 Ω System Reference Level Conversion	6-2	
6-2	Marker Trace Organization	6-10	
7-1	Power Cord Options	7-1	
7-2	Extended Service and Warranty Options	7-2	
7-3	Option 05 Alternate Specifications	7-2	
7-4	Option 07 Alternate Specifications	7-3	
7-5	Options 30 and 31 Characteristics and Alternate Specifications	7-5	
7-6	Option 42 Alternate Specifications	7-5	